

File

October 8, 1963

M E M O: For the record.

Subject: Inland Lake Reservoir

By: James N. Ward

* * * * *

Re: Burnt Fork

October 8, 1963 said reservoir was inspected with respect to some distribution problems which have been created over the irrigation company's storage water and the natural flow water. The water leaving the lake through the existing gate was about 3 to 5 c.f.s. This appeared to be about the same or less than the water coming in the lake.

The structure immediately below the outlet pipe is in need of repair in order to make it an acceptable measuring device. It needs to be leveled and reconstructed so that water will not go under and around the structure.

JNW/wh